


PZA22

Different Dia of Union Cross(2/2)




MODEL [ØD-T]

Tube (Metric) - Thread(R)		
MODEL	ØD1	ØD2
PZA22 08-06	8	6
PZA22 10-08	10	8
PZA22 12-10	12	10

PZA31

Different Dia of Union Cross(3/1)




MODEL [ØD-T]

Tube (Metric) - Thread(R)		
MODEL	ØD1	ØD2
PZA31 08-06	8	6
PZA31 10-08	10	8
PZA31 12-10	12	10

PMM

Bulkhead Union




MODEL [ØD-T]

Tube (Metric) - Thread(R)	
MODEL	ØD
PMM 04	4
PMM 06	6
PMM 08	8
PMM 10	10
PMM 12	12

PPM

Bulkhead Union P




MODEL [ØD-T]

Tube (Metric) - Thread(R)	
MODEL	ØD
PPM 04	4
PPM 06	6
PPM 08	8
PPM 10	10
PPM 12	12

PLM

Bulkhead Union P




MODEL [ØD-T]

Tube (Metric) - Thread(R)	
MODEL	ØD
PLM 04	4
PLM 06	6
PLM 08	8
PLM 10	10
PLM 12	12

PCP

Straight Ace Coupler Plug



MODEL [ØD-T]

Tube (Metric) - Thread(R)	
MODEL	ØD
PCP 04	4
PCP 06	6
PCP 08	8
PCP 10	10
PCP 12	12
PCP 16	16