


PUT

Union Tee




MODEL [ØD-T]

Tube (Metric) - Thread(R)

MODEL	ØD
PUT 04	4
PUT 06	6
PUT 08	8
PUT 10	10
PUT 12	12
PUT 16	16

PY

Union Y




MODEL [ØD-T]

Tube (Metric) - Thread(R)

MODEL	ØD
PY 04	4
PY 06	6
PY 08	8
PY 10	10
PY 12	12

PG

Reducer




MODEL [ØD-T]

Tube (Metric) - Thread(R)

MODEL	ØD1	ØD2
PG 06-04	6	4
PG 08-04	8	4
PG 08-06	8	6
PG 10-06	10	6
PG 10-08	10	8
PG 12-08	12	8
PG 12-10	12	10
PG 16-12	16	12

PUG

Different Dia of Union Tee




MODEL [ØD-T]

Tube (Metric) - Thread(R)

MODEL	ØD1	ØD2
PUG 06-04	6	4
PUG 08-04	8	4
PUG 08-06	8	6
PUG 10-06	10	6
PUG 10-08	10	8
PUG 12-08	12	8
PUG 12-10	12	10

PW

Reducer Y




MODEL [ØD-T]

Tube (Metric) - Thread(R)

MODEL	ØD1	ØD2
PW 06-04	6	4
PW 08-04	8	4
PW 08-06	8	6
PW 10-06	10	6
PW 10-08	10	8
PW 12-08	12	8
PW 12-10	12	10

PZA

Union Cross



MODEL [ØD-T]

Tube (Metric) - Thread(R)

MODEL	ØD
PZA 04	4
PZA 06	6
PZA 08	8
PZA 10	10
PZA 12	12